


EUROBOLT FASTENERS

www.euroboltbg.com ; e-mail:office@euroboltbg.com ; tel./fax.: + 359 (2) 931 81 21

Прес гайка RBR


Гайка за пресоване в метал



| d | M 2.5 | M 3 | M 3.5 | M 4 | M 5 | M 6 | M 8 | M 10 | M 12 |
|--------|-------|------|-------|------|------|------|-------|-------|-------|
| A | 5.54 | 5.54 | 6.73 | 6.73 | 7.92 | 9.52 | 12.7 | 15.87 | 19.05 |
| B | 7.92 | 7.92 | 9.52 | 9.52 | 11.1 | 12.7 | 15.87 | 19.05 | 25.4 |
| C | 3.17 | 3.17 | 3.17 | 3.17 | 3.81 | 5.08 | 6.35 | 7.62 | 10.16 |
| h / φ | 5.54 | 5.54 | 6.73 | 6.73 | 7.92 | 9.52 | 12.7 | 15.87 | 19.05 |
| 1.0 мм | @ | OK | @ | OK | OK | OK | OK | OK | |
| 1.2 мм | @ | OK | @ | OK | OK | OK | OK | OK | |
| 1.6 мм | @ | OK | @ | OK | OK | OK | OK | OK | |
| 2.0 мм | @ | OK | @ | OK | OK | OK | OK | OK | |
| 2.5 мм | @ | OK | @ | OK | OK | OK | OK | OK | @ |
| 3.0 мм | @ | OK | @ | OK | OK | OK | OK | OK | @ |

Прес гайка SCFR

Заклинваща гайка в метал



| d | M 2.5 | M 3 | M 3.5 | M 4 | M 5 | M 6 | M 8 | M 10 | |
|-------|-------|------|-------|------|------|-------|-------|-------|--|
| D | 4.22 | 4.22 | 4.73 | 5.38 | 6.38 | 8.72 | 10.44 | 13.97 | |
| B | 6.3 | 6.3 | 7.1 | 7.9 | 8.7 | 11.05 | 12.65 | 17.35 | |
| H | 1.5 | 1.5 | 1.5 | 2.0 | 2.0 | 4.1 | 5.5 | 7.48 | |
| h / φ | 4.25 | 4.25 | 4.75 | 5.4 | 6.4 | 8.75 | 10.5 | 14 | |
| 0.8мм | @ | OK | @ | OK | OK | | | | |
| 1.0мм | @ | OK | @ | OK | OK | | | | |
| 1.4мм | @ | OK | @ | OK | OK | OK | OK | | |
| 2.3мм | | | | | | OK | OK | OK | |
| 3.2мм | | | | | | | | OK | |

OK на склад / on stock

@ с поръчка / in request

EUROBOLT FASTENERS

www.euroboltbg.com ; e-mail:office@euroboltbg.com ; tel./fax.: + 359 (2) 931 81 21

Прес гайка KS

Заклинваща гайка в метал



| М | М 2.5 | М 3 | М 4 | М 5 | М 6 | М 8 | М 10 | М 12 | М 16 |
|---------|-------|-----|-----|------|-----|------|-------|-------|-------|
| d1 | 4.5 | 4.5 | 5.5 | 6.5 | 8.0 | 10.0 | 12.5 | 14.5 | 18.5 |
| d2 | 4.7 | 4.7 | 5.7 | 6.75 | 8.3 | 10.3 | 12.85 | 14.85 | 18.85 |
| h | 3.0 | 3.0 | 3.2 | 4.0 | 5.0 | 6.5 | 8.0 | 10.0 | 13.0 |
| h1 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.8 | 1.8 | 2.8 | 2.4 |
| φ отвор | 4.5 | 4.5 | 5.5 | 6.5 | 8.0 | 10.0 | 12.5 | 14.5 | 18.5 |
| AF | 5.5 | 5.5 | 7 | 8 | 10 | 13 | 15 | 17 | 22 |
| 1.0мм | @ | OK | OK | OK | OK | | | | |
| 2.0мм | | | | | | OK | OK | | |
| 3.0мм | | | | | | | | OK | OK |

Прес гайка KM

| М | М 2.5 | М 3 | М 4 | М 5 | М 6 | | | | |
|---------|-------|-----|-----|------|-----|--|--|--|--|
| d1 | 4.5 | 4.5 | 5.5 | 6.5 | 8.0 | | | | |
| d2 | 4.7 | 4.7 | 5.7 | 6.75 | 8.3 | | | | |
| h | 3.0 | 3.0 | 3.2 | 4.0 | 5.0 | | | | |
| h1 | 1.4 | 1.4 | 1.4 | 1.4 | 1.4 | | | | |
| φ отвор | 4.5 | 4.5 | 5.5 | 6.5 | 8.0 | | | | |
| AF | 5.5 | 5.5 | 7 | 8 | 10 | | | | |
| 1.5мм | @ | OK | OK | OK | OK | | | | |

Прес гайка KL

| М | М 2.5 | М 3 | М 4 | М 5 | М 6 | | | | |
|---------|-------|-----|-----|------|-----|--|--|--|--|
| d1 | 4.5 | 4.5 | 5.5 | 6.5 | 8.0 | | | | |
| d2 | 4.7 | 4.7 | 5.7 | 6.75 | 8.3 | | | | |
| h | 3.0 | 3.0 | 4.5 | 5.0 | 5.0 | | | | |
| h1 | 1.8 | 1.8 | 1.8 | 1.8 | 1.8 | | | | |
| φ отвор | 4.5 | 4.5 | 5.5 | 6.5 | 8.0 | | | | |
| AF | 5.5 | 5.5 | 7 | 8 | 10 | | | | |
| 2.0мм | @ | OK | OK | OK | OK | | | | |

OK на склад / on stock

@ с поръчка / in request